

EA-6B HVOF-Coated Landing Gear: Post-Deployment Inspection Results

Tai Ngin
Materials Engineer
NAVAIR FRCSE, 43410

Report Documentation Page				Form Approved OMB No. 0704-0188	
Public reporting burden for the collection of information is estimated to average 1 hour per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden, to Washington Headquarters Services, Directorate for Information Operations and Reports, 1215 Jefferson Davis Highway, Suite 1204, Arlington VA 22202-4302. Respondents should be aware that notwithstanding any other provision of law, no person shall be subject to a penalty for failing to comply with a collection of information if it does not display a currently valid OMB control number.					
1. REPORT DATE SEP 2009		2. REPORT TYPE		3. DATES COVERED 00-00-2009 to 00-00-2009	
4. TITLE AND SUBTITLE EA-6B HVOF HVOF-Coated Landing Gear: Post Post-Deployment Inspection Results				5a. CONTRACT NUMBER	
				5b. GRANT NUMBER	
				5c. PROGRAM ELEMENT NUMBER	
6. AUTHOR(S)				5d. PROJECT NUMBER	
				5e. TASK NUMBER	
				5f. WORK UNIT NUMBER	
7. PERFORMING ORGANIZATION NAME(S) AND ADDRESS(ES) Naval Air Station ,Fleet Readiness Center Southeast (FRCSE),Jacksonville,FL				8. PERFORMING ORGANIZATION REPORT NUMBER	
9. SPONSORING/MONITORING AGENCY NAME(S) AND ADDRESS(ES)				10. SPONSOR/MONITOR'S ACRONYM(S)	
				11. SPONSOR/MONITOR'S REPORT NUMBER(S)	
12. DISTRIBUTION/AVAILABILITY STATEMENT Approved for public release; distribution unlimited					
13. SUPPLEMENTARY NOTES ASETSDefense 2009: Sustainable Surface Engineering for Aerospace and Defense Workshop, August 31 - September 3, 2009, Westminster, CO. Sponsored by SERDP/ESTCP.					
14. ABSTRACT					
15. SUBJECT TERMS					
16. SECURITY CLASSIFICATION OF:			17. LIMITATION OF ABSTRACT Same as Report (SAR)	18. NUMBER OF PAGES 27	19a. NAME OF RESPONSIBLE PERSON
a. REPORT unclassified	b. ABSTRACT unclassified	c. THIS PAGE unclassified			

Outline

- Background
- HVOF Procedure
- Previous Results
- EA-6B Results
- Future Work



Background

- Electrolytic hard chrome (EHC)
 - Wear resistance
 - Corrosion resistance
- Uses hexavalent chromium (Cr^{6+})
 - Carcinogen, OSHA controlled
 - Expensive to dispose



Background

- IPT's for chrome alternatives
 - HCAT: Hard Chrome Alternatives Team
 - ESTCP: Environmental Strategic Technology Certification Program
 - JG-PP: Joint Group on Pollution Prevention
- Validation Project: HVOF Thermal Spray
 - Environmentally acceptable
 - Superior performance to EHC


Background

- High Velocity Oxygen Fuel (HVOF)
 - Environmental Coatings
 - Wear Resistant Coatings
- FRCSE Applications
 - F404, F414, J52, TF34
 - Drive shafts, combustor cans



HVOF Procedure

- HVOF Process
 - Combustion of fuel gas and oxidizer (accelerant gas)
 - Feed powder into supersonic gas stream
 - Impact particles onto surface with high temperature and high velocity





HVOF Procedure

- HVOF Advantages
 - Low porosity
 - High hardness
 - High adhesive bond strength
 - Higher density
- Fits into NAVAIR LEAN Processes
 - Increases throughput
 - Decrease turn around time
 - Reduce costs and simplifies work processes



HVOF Procedure

- HVOF Coating
 - METCO DIAMALLOY 2005 NS
 - 83WC-17Co powder mixture
 - Advantages over EHC
 - Hardness
 - Wear Resistance
 - Fatigue Resistance



HVOF Procedure

- Concerns for HVOF
 - Unknown response for:
 - Carrier-based landings
 - Saltwater corrosive environments
 - Coating susceptible to aqueous and gaseous corrosion
 - Require validation and demonstration in actual naval environments

Previous Work

- Timeline

- 10/1999: EA-6B Landing Strut HVOF coated


- Spalling issues
 - High strains at large stresses
 - Flight clearance on hold

- 09/2004: EA-6B successfully landed on USS Carl Vinson
 - HVOF coating successful
 - Major project milestone



EA-6B Landing Gear

- Current Landing Gear Strut Piston
 - AISI 4330 V Mod
 - $\sigma_Y = 180\text{-}185$ ksi
 - $\sigma_{UTS} = 220\text{-}240$ ksi
 - Coated
 - METCO DIAMALLOY 2005 NS
 - Ground finished
 - $R_a = 8\text{-}16$ μin
 - Superfinished
 - $R_a = 2\text{-}4$ μin




EA-6B Results

- EA-6B (163395) Tours of Duty
 - 2004-2005 VAQ 138/142
 - 2005-2009 VAQ 209 (Reserve Squad)
- Relatively short time-at-sea
 - 153 Catapult shots
 - 154 Arrested landings

Year	Flight Hours	Landings
2004	33	10
2005	605	207
2006	543	177
2007	192	85
2008	109	54
2009	70	38
Total	1552	571

EA-6B Results

- Strut Disassembly
 - Performed due to leak in lower seal





HVOF coated axle and piston
during tear down



HVOF coated piston during
disassembly

EA-6B Results

- Collar Assembly
 - No indications of wear or other damage



EA-6B Results

- Collar Assembly
 - Roughness check

HVOF coated area

Surface finish $R_a = 7 \mu\text{in}$;
 $R_a = 10\text{-}11 \mu\text{in}$ at outer most
edge shown

Chrome plated area

Surface finish $R_a = 6\text{-}7 \mu\text{in}$



EA-6B Results

- HVOF Axle

HVOF on Axle Journals, edges in good condition, coating appeared to be in very good condition



EA-6B Results



- Collar Bushing
 - The original item was discarded after disassembly
 - Operators reported part corroded
 - Corrosion typical for this part in service.



EA-6B Results

- Failed Seal


- Seal wear (“flat spots”) at 0° and 180°
- Possible service in Middle East: sand entrapment / intrusion issues
- Failure analysis will be performed by Trelleborg Sealing Solutions (POC: John Nash)



EA-6B Results

- Strut Disassembly - Barrel

- Visual Inspection
 - Roughness Check
- Clean
- Vapor Degrease
- Fluorescent Penetrant Inspection (FPI)
- Re-superfinish
 - Recheck roughness



Disassembly of collar and seal retainer in location of leak


EA-6B Results

- HVOF Piston Surface
 - Roughness check

Surface finish measured Ra 3-4 μin

Surface finish Ra 8-10 μin in center section

Surface finish measured Ra 11-18 μin in area 2" to 8" from base



EA-6B Results

- HVOF Piston Surface
– Upper Seal Area




Finish Roughness (Ra) = 2-3 μin



EA-6B Results

- HVOF Piston Surface
– Lower Seal Area



EA-6B Results

- Corrosion issues
 - FPI initially found no indications
 - After superfinishing, pits found in the coating
 - Co binder highly susceptible to salt corrosion



Future Work

- First/Best option: Keep Current Coating
 - Re-superfinish current pitted HVOF coating
- Goal: Remove pits, establish Ra of 2-4 μin
 - Want coating thickness above minimum tolerance
 - If not, then part is in a state of Functionally Unusable Component Technology

Future Work

- **Second/Last option: Apply New Coating**
 - Grind pitted coating to parent metal
 - Recoat the part to return to service
 - Apply chrome coating -OR-
 - Reapply HVOF coating
- **Complications**
 - Future HVOF coating choice
 - DIAMALLOY 2005: 83WC-17Co
 - AMDRY 5843 (AMS 2447-9): 86WC-10Co-4Cr
 - **FUNDING!?!?**
 - *“Hubba, hubba, hubba, money, money, money...who do you love?”*



Acknowledgments



- Luis Carney
 - Senior Materials Engineer, FRCSE 43410



- Jon Devereaux
 - Materials Engineer, NASA KSC



- Erik Mueller
 - Materials Engineer, FRCSE 43410



- Steve Sabatella
 - EA-6B FST Engineer, FRCSE 43310



- Richard Vander Straten
 - HVOF Program Manager, ES3

Questions?



Due to NAVAIR restrictions, responses to questions are not authorized.